Joy, IL September 2022 Council Report

Water System

I wanted to sample Well 2 a few more times to make sure it continued to pass the bacteria sampling. It has failed each time I've resampled. Something must be getting back into the pipe. Most likely it will need televised to look for breaks or an issue with a joint.

I've been talking to Gary at Farnsworth about the issues in general with Well 2. From the VFD to the samples not passing, we need to finally be able to crack this code. He is going to get Valley Construction involved as he feels they are still responsible considering they did the pipe work.

I'm still trying to get work scheduled with Tri-City Electric for the VFD but have not had great luck. Again, I brought Gary in this to try to push them to figure out the problem.

Kurita sent us a new meter. Unfortunately, they refuse to send us one that is not a drop in fit. The one that was sent would have to be completely re-plumbed at our cost. I'm working with the engineer on this. I know the exact meter I want, and it would be cheaper than the one they sent, so I don't understand why they have an issue.

We have the salt dialed in pretty well at this point. We are only using a bag or two a day. I'm going to adjust just a little more. I'd like to get us to one bag a day if possible while maintaining the same level of hardness.

Wastewater System

Nothing to report, everything is running fine currently.

Chad McCleary
Ion Environmental Solutions