

Joy Council Report – November 2025

Water System

I noticed flows were abnormally high which indicates a leak in the system. We've been searching for the source of the leak but cannot find it. We should know more by the time of the council meeting, so I'll provide an update in person.

The new quill for the chlorine injection system has been ordered. It will be around \$400.

Rather than having backup parts for chlorine injection system pumps in each individual system we operate, we decided as a company to stock Stenner parts. We will use our stock to replace items in the city and bill the city as needed.

Salt tank has been cleaned out and it is filled and back to normal functioning.

As previously reported, we will complete a second round of lead and coppers before the end of the year. Additionally, there is a new requirement for sampling childcare and school facilities for lead. The first round of this sampling is also due before year end.

Wastewater System

All samples were in compliance for October and all is running smoothly.

Chad McCleary

Ion Environmental Solutions