

Joy, IL October 2022 Council Report

Water System

The pressure test passed for Well 2 which means that we should not have a leak. However, when we went to flush the line with water, we got next to no water coming from the well. We need to have someone come pull the well and see what's going on. Cahoy gave me a ballpark figure and said that it would be less than \$5000 to come inspect everything. That has to be the next step.

I lowered the tower level a few feet to make sure we get a little more turn over during the winter months.

Salt use has been pretty consistent at 1-2 bags a day.

Overall, if we can tackle Well 2, the plant is running fine.

Wastewater System

We are having the generator serviced in the next few weeks.

Chad McCleary
Ion Environmental Solutions