Joy, IL December 2023 Council Report

Water System

Lead/coppers are done for year.

Well has been running well. Britton had made some adjustments at the site and we're no longer having issues with faults and failures. There is still a small line filter they plan to install. That is on order and we're just waiting for it to come in.

We're having an issue with the transducer that reads the level in the brine tank. They didn't plumb it with a union, so we're gonna have to cut into the pipe to check this out. We're going to buy a couple of fittings for that. Shouldn't be more than \$20 or so. We think the line is just full of sediment from the tank and is causing the transducer to read incorrectly periodically. It's more of an intermittent issue.

Wastewater System

Nothing of note for the wastewater system.

Chad McCleary

Ion Environmental Solutions