

Joy Council Report – October 2025

Water System

We need to install a new quill for the chlorine injection system. We need a few backup replacement parts for the chlorine injection system pumps. I'll put a quote together.

We are in the process of cleaning out the salt tank. Over time it gets dirty. The city may notice for a day or two that the hardness levels will go up during this process, but it will go back to normal after this process is complete.

All required sampling for quarter 3 has been completed. We need to complete a second round of lead and coppers before the end of the year.

Wastewater System

All samples were in compliance for September and all is running smoothly.

Chad McCleary

Ion Environmental Solutions